



The below pictures were provided By Terra Sun Energy LLC.. TEMP-COAT 101 was utilized as part of an energy efficiency makeover of a home located in Salt Lake City Utah. The home was losing a significant amount of heat due to poorly insulated wall and windows. The interior of the home was sprayed with 30mils of TEMP-COAT 101 and the windows replaced. The infrared study below shows the drastic improvement of the homes ability to retain heat during the cold winter months.



Painting un-insulated walls



Painting floor thermal over cement

Heat loss is the yellow & orange



Heat stays in in blue purple

